

G-III-B-127

ca. 1900

Otto Goehringer Farm
Private
Accident vic.

The Otto Goehringer Farm consists of a house and barn. The house is a two-story, gable-roofed, ell-plan dwelling with a symmetrical, two-bay facade.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

AND/OR COMMON

Otto Goehringer Farm

2 LOCATION

STREET & NUMBER

Route 219S , W. side, approx .2 mile S. of Accident

CITY, TOWN

Accident

☒ VICINITY OF

CONGRESSIONAL DISTRICT
6th

STATE

Maryland

COUNTY

Garrett County

3 CLASSIFICATION

CATEGORY

☐ DISTRICT

☒ BUILDING(S)

☐ STRUCTURE

☐ SITE

☐ OBJECT

OWNERSHIP

☐ PUBLIC

☒ PRIVATE

☐ BOTH

PUBLIC ACQUISITION

☐ IN PROCESS

☐ BEING CONSIDERED

STATUS

☒ OCCUPIED

☐ UNOCCUPIED

☐ WORK IN PROGRESS

ACCESSIBLE

☐ YES: RESTRICTED

☐ YES: UNRESTRICTED

☒ NO

PRESENT USE

☐ AGRICULTURE

☐ COMMERCIAL

☐ EDUCATIONAL

☐ ENTERTAINMENT

☐ GOVERNMENT

☐ INDUSTRIAL

☐ MILITARY

☐ MUSEUM

☐ PARK

☒ PRIVATE RESIDENCE

☐ RELIGIOUS

☐ SCIENTIFIC

☐ TRANSPORTATION

☐ OTHER

4 OWNER OF PROPERTY

NAME

Otto Goehringer

Telephone #:

STREET & NUMBER

CITY, TOWN

☐ VICINITY OF

STATE, zip code

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,

REGISTRY OF DEEDS, ETC.

Garrett County Courthouse

STREET & NUMBER

Third and Alder Streets

CITY, TOWN

Oakland

STATE

Maryland 21550

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

None

DATE

☐ FEDERAL ☐ STATE ☐ COUNTY ☐ LOCAL

DEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

G-I-B-27

CONDITION

☐ EXCELLENT
☒ GOOD
☐ FAIR
☐ DETERIORATED
☐ RUINS
☐ UNEXPOSED

CHECK ONE

☒ UNALTERED
☐ ALTERED

CHECK ONE

☒ ORIGINAL SITE
☐ MOVED DATE _____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Otto Goehringer Farm is located west of Rt 219S, just south of the town of Accident. The farm stands high on a hill, overlooking the highway and consists of a house and barn.

The house is a two-story, gable-roofed, ell-plan dwelling with a symmetrical, two-bay facade. The facade points southeast and its first floor is covered with a hipped-roofed porch. On the northeast elevation, the ell is filled with a one-story, enclosed, shed-roofed porch.

The house rests on a low stone foundation and is covered with aluminum siding over German siding. The windows are 2/2 sash with mitred surrounds. The facade door, in the east bay of the facade, has two glass panels in its upper half.

The roof is slate. The house has two stove chimneys: an interior brick chimney at the southwest gable end of the main block, and an exterior cinderblock chimney on the northeast gable end of the main block. The facade porch has an asphalt roof supported by square posts.

Southwest of the house is a small gable-roofed board and batten garage, and southeast of the garage is a frame bank barn. The bank entrance points northwest. The barn has a stone foundation, vertical board-covered walls painted red, and a corrugated metal roof. On either gable end are painted two white five-pointed stars.

CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

G-II-8-127

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input checked="" type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES	ca. 1900	BUILDER/ARCHITECT	unknown
----------------	----------	-------------------	---------

STATEMENT OF SIGNIFICANCE

This house is an example of a common western Maryland type. Houses of this general configuration, a rectangular main block and rear kitchen wing, were constructed in Garrett County from the late nineteenth through the early twentieth centuries.

CONTINUE ON SEPARATE SHEET IF NECESSARY

9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _____

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE

COUNTY

STATE

COUNTY

11 FORM PREPARED BY

NAME / TITLE

Ann Burns, Historic Sites Surveyor

ORGANIZATION

Maryland Historical Trust/Bureau of Mines

DATE

1981

STREET & NUMBER

Shaw House, 21 State Circle

TELEPHONE

(301) 269-2438

CITY OR TOWN

Annapolis

STATE

Maryland 21401

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

G-III-B

STATE OF MARYLAND
MARYLAND GEOLOGICAL SURVEY

KEYSERS RIDGE (JUNC. U. S. 40) 7.3 MI.
20' KAESE MILL 2.3 MI.

5163 III NE
(ACCIDENT)

646

17'30"

647



McHenry, MD
USGS 7.5 Minute Series
Scale - 1:24,000
1947; photorevised 1974

Site #: G-III-B-127
Otto Goehringer Farm
W. side of Rt. 219S, approx .2 mile S. of Accident
Accident vic.



G-III-B-127

Otto Goehringer *Farm*

Garrett Co., MD

Ann Burns 7/30/81

Facade: SE elev.



G-III-B-127

Otto Goehringer FARM

Garrett Co., MD

Ann Burns 7/30/81

NE & NW elevs.